



HAZARD ALERT

Failure to conduct Management of Change (MOC) leads to fatality

On December 3rd, 2012, a maintenance employee at an oil refinery was fatally injured when a rotameter failed and a mixture of propane and hydrofluoric acid (HF) was released. The rotameter was part of a temporary installation on a pump seal flush line to determine flow to the pump seal.

A temporary line was run from the flush line header to a flare header. A pressure gauge was placed in the line to determine flow. A rotameter was also added for a visual reference. The rotameter was rated for 200 psi but the flush line had an operating pressure of between 260 and 280 psi. The rotameter also had a glass face, which is not compatible with HF service.

No Management of Change (MOC) was conducted prior to the development of this plan or this installation being put into service.



- ◆ For any Process Safety (29 CFR 1910.119) covered facility, prior to any change that is not in kind, you must conduct a Management of Change (MOC)
- ◆ If you are unsure of the need for a MOC, refer to your facility's written plan and 29 CFR 1910.119 (I).
- ◆ Be sure to address the following considerations:
 - The technical basis for the proposed change
 - Impact of change on safety and health
 - Modifications to operating procedures
 - Necessary time period for the change
 - Authorization requirements for the proposed change
- ◆ Employees must be effectively trained in all elements of the Process Safety standard.



5 Gateway Center
Pittsburgh, PA 15222
safety@usw.org
412.562.2581

This hazard alert is based on an actual incident, and reflects our best understanding of the incident at the time it was written. However, many incidents have multiple causes; this alert may not cover all of them. The purpose of the alert is to illustrate workplace hazards; it is not intended to be a comprehensive report on the incident.